NIX . 03,4

25X1A

25X1A

Approved For Release 2002/10/16 : CIA-RDP63-00313A000500120025-7

9 October 1963	
MEMORANDUM FOR: Deputy Director (Science and Technology)	
SUBJECT : Daily Activity Report - 9 October 1963	
1. Mission Status	
a. IDEALIST - The detachments at and Edwards Air Force Base, California are presently on standby.	
Flight #3230 at is scheduled to make a flight this evening at 2100E hours over the Nepal border and Tibet.	
b. BRASS KNOB - None scheduled.	
c. SATELLITES - CORONA/J Mission #1002-2 is still inopera	itive.
2. OXCART Status, # October:	
a. Aircraft #121 bypass area being reworked at engine face. Article scheduled for flight 10 October 1963.	
b. Aircraft #122 reworking spike and bypass control to correct hydro fluctuations. No ETIC.	:t
c. Aircraft #124 made training flight 8 October 1963. See flig report for other details.	ht
d. Aircraft #125 training mission cancelled due to weather. Mission rescheduled for 9 October, weather permitting.	
e. Aircraft #126 out of commission for removal of engine #125 for scheduled overhaul. No ETIC.	ż
SEGREI	
Approved For Release 2002/10/16 : CIA-RDP63-00313A000500120025-7	

25X1A

25X1A

Approved For Release 2002/10/16 : CIA-RDP63-00313A000500120025-7

-3392-63 25X1A

- f. Aircraft #127 is awaiting fins. No ETIC.
- g. Aircraft #128 is awaiting fins. No ETIC. FOD suffered 4 October is minor. The first stage is being blended. No ETIC.
- h. Aircraft #129 is scheduled for flight this morning at 1000 hours area time.
 - i. Aircraft #130 is in reassembly. No ETIC.
- j. Aircraft #1001 is cancelled 8 October 1963 due to hydro pressure gauge malfunctions. Scheduled for flight 9 October 1963.
 - k. Aircraft #1902 is in reassembly. No ETIC.
- 3. OXCART Flights, 8 October 1963:
- a. Aircraft #122: Flew a "heat soak" mission at a maximum of M2.14. Flight experienced slight inlet roughness at M2.14 but otherwise uneventful.
- b. Aircraft #124: Instructor Pilot check out. Flight remained in local area, was successful and uneventful.